



## Full Petrol Vehicle Report

**Inspection Report No:** PET10064

**Inspector Name:** Shane Edwards

**Inspector Email:** shane@kickthetyres.co.nz

This vehicle inspection report involves only an external examination of the vehicle and the carrying out of the road tests indicated. Unless otherwise stated in this report, no dismantling of any part of the vehicle has been undertaken

**IMPORTANT NOTICE:** Faults that could only be found by internal inspection or partial dismantling of the vehicle will not therefore be discovered. The report only relates to the condition of the vehicle as revealed by external inspection and road tests on the date that the report was completed.

For full terms and conditions please visit our website: [www.kickthetyres.co.nz](http://www.kickthetyres.co.nz)

### Owner and Vehicle Description

<b>Purchaser's Name</b> Sample Wilson	<b>Purchaser's Phone</b> 55555555	<b>Purchaser's Email</b> samplewilwson@gmail.com
<b>Car Make</b> 2012 Mazda MX5 - Petrol	<b>Car Rego. Number</b> sample	<b>Car Odometer kms/MIs</b> 106,477km.
<b>WOF Expiration Date</b> 15/10/2025	<b>Registration Expiry Date</b> 15/03/2025	<b>Booked Through</b> Branch
<b>Weather</b> Dry	<b>Light</b> Good	<b>Vehicle</b> Clean
<b>Oil Level</b> Ok	<b>Max Road Test Speed</b> 70 kph	<b>Normal Operating Temperature</b> Yes

**General Comment:** Good driving popular 6 speed manual MX5 presented in tidy condition for its age and mileage. Some items to note on report but generally a sound example.

## Items covered by this inspection

### 1. Cooling System

**Pass** - Radiator

**Pass** - Belts

**Pass** - Cooling Fan

- - Other

**Pass** - Radiator Cap

**Pass** - Water Pump

**Pass** - Thermostat

**Pass** - Hoses

**Pass** - Frost Plugs

**Pass** - Heater

### 2. Motor Electrics

**Pass** - Battery

**Pass** - Generator/Alternator

- - Other

**Pass** - Terminals

**Pass** - Starter Motor

**Pass** - Leads

**Pass** - Solenoid

### 3. Instruments

**Pass** - Horn

**Pass** - Screen Washers Front

**Pass** - Front Lights

**Pass** - Hazard Lights

**Pass** - Radio

- - Other

**Pass** - Wipers Front

**N/A** - Screen Washers Rear

**Pass** - Rear Lights

**Pass** - Gauges

**Pass** - Heater/Fan

**N/A** - Wipers Rear

**Pass** - Indicators

**Pass** - Warning Lights

**Pass** - Instruments

**Pass** - Heater/Air Cond.

### 4. Tyres - 1.5mm Legal, 7-8mm New Average

- - L.F

- - R.R

- - R.F

- - Spare

- - L.R

**Advisory** - Wheels

### 5. Underbody

**Pass** - Chassis/Mountings

**Pass** - Cables & Wires

**Pass** - Engine Mountings

**Pass** - Hoses & Tubes

**Pass** - Clutch

- - Other

### 6. Exhaust System

**Pass** - Manifold

**Pass** - Clamps

- - Other

**Pass** - Pipes

**Pass** - Brackets

**Pass** - Mufflers

**Pass** - Connections

## 7. Steering & Suspension Front

<b>Pass</b> - Steering Wheel	<b>Pass</b> - Steering Column	<b>N/A</b> - Steering Box
<b>Pass</b> - Steering Rack	<b>Pass</b> - Steering Linkages	<b>Pass</b> - Steering Arms
<b>Pass</b> - Power Steering Pump	<b>Pass</b> - Swivel Joints	<b>Pass</b> - Control Arms - Upper
<b>Pass</b> - Control Arms - Lower	<b>Pass</b> - Shock Absorbers	<b>Pass</b> - R.H. Wheel Bearings
<b>Pass</b> - L.H. Wheel Bearings	<b>Pass</b> - Springs	<b>Pass</b> - Suspension Units
<b>Pass</b> - Suspension Mounts	<b>Pass</b> - Torsion Bars	<b>Pass</b> - Anti-roll Bars & Bushes
<b>Pass</b> - Rubber Boots	<b>Pass</b> - Wheel Alignment	<b>Pass</b> - Wheel Balance
- - Other		

## 8. Rear Suspension

<b>Pass</b> - Control Arms	<b>Pass</b> - Bushes & Pins	<b>Pass</b> - Shock Absorbers
<b>Pass</b> - Springs & Mounts	<b>Pass</b> - R.H. Wheel Bearing	<b>Pass</b> - L.H. Wheel Bearing
<b>Pass</b> - Suspension Mounts	- - Other	

## 9. Drive Shaft & Joints

<b>Pass</b> - Front Universal Joint	<b>Pass</b> - Centre Universal Joint	<b>Pass</b> - Rear Universal Joint
<b>N/A</b> - R.H. Universal Joint	<b>N/A</b> - L.H. Universal Joint	<b>N/A</b> - R.H. CV Joint
<b>N/A</b> - L.H. CV Joint	- - Other	

## 10. Brakes

<b>Pass</b> - Hoses	<b>Pass</b> - Cables	<b>Pass</b> - Servo & Booster
<b>Fail</b> - Master Cylinder	<b>Pass</b> - Disc Pads (where visible)	<b>Pass</b> - Discs (where visible)
<b>N/A</b> - ABS Operation	- - Other	

## 11. Motor

<b>Pass</b> - Compressions	<b>Pass</b> - Pistons & Rings	<b>Pass</b> - Bearings
<b>Pass</b> - Valve Train	<b>Fail</b> - Oil Leaks	<b>Pass</b> - Oil Condition
- - Oil Level	<b>Pass</b> - Fuming	<b>Pass</b> - Tuning
- - Other		

**12. Road Test****Pass** - Clutch**Pass** - Gearbox**N/A** - Automatic  
Transmission**Pass** - Differential**Advisory** - Foot Brake**Pass** - Hand Brake

- - WOF Expiration date

- - Other Certificates (Road User Charges,  
Self Containment etc).

- - Registration Due:

- - Other

**13. Body & Trim****Pass** - Water Leaks**Pass** - Bumpers**Pass** - Exterior Trim-  
Chrome**Pass** - Mirrors**Pass** - Rubbers & Seals**Pass** - Interior Trim**Pass** - Upholstery**Pass** - Knobs & Handles**Pass** - Windows**Pass** - Doors**Pass** - Light Lenses & Reflectors**Pass** - Carpets**Pass** - Interior Light**Fail** - Jack**Pass** - Wheel Brace**Pass** - Dash Panels**Pass** - Bonnet Release**Pass** - Boot Release**Pass** - Seats

- - Other

**14. Body Report****Pass** - Perforation Rust**Pass** - Surface Rust**Pass** - Rust Spots**Advisory** - Scratches/Abrasion**Pass** - Paint Failure**Advisory** - Dents**Pass** - Minor Panel Repairs**Pass** - Improper Alignment**Pass** - Other

- - Paint Repair Done

- - Rust Repair Done

- - Accident Repair  
Done*Note: Please find the comment or image on the last page.*

## Additional Checks

1. Compression Test.pdf
2. 12v Battery System Test.pdf

*Note: Please find the attached PDF on your email.*

## Stamps

- *Due to age, modifications, shown kms, or overall condition of this vehicle NO responsibility for future failures or items not noted on this inspection sheet can be accepted.*
- **Air Bags (SRS):** *As there is no practical method of testing the operation of these units, NO responsibility for the non-operation or any failure of these items can be accepted.*
- **Cambelt:** *As checking the condition of the cambelt in many vehicles requires some dis-assembly, this is not practical to undertake. We can only advise if the vehicle has any indication (decal, mechanics markings etc.) the cambelt has been replaced. If you have doubts please ask to sight a receipt or other proof of the cambelt having been replaced.*
- *No signs of any major body repairs or rusting in the critical zones. As usual, some minor cosmetic touch ups have been undertaken and some minor marks, dents and/or blemishes may remain. Apart from any marked items, everything is within specifications or tolerances reflecting the age and distance the vehicle has travelled.*
- *Radio means Tuner operation and gives no indication of frequency or quality. CD, Tape deck or any other input may not have been tested.*

**"Don't forget to check out our Tips and Advice for Buying Used Vehicles guide on our website!" It contains useful information on other things to consider when buying a used vehicle e.g checking if there is money owing on the vehicle.**

## Comment and Images

### 1. Cooling System

**Pass** - Radiator

**Comment:** Coolant in good condition, no leaks in system.

### 2. Instruments

**Pass** - Heater/Air Cond.

**Comment:** Heats to 81 degrees, cools to 6 degrees as measured at centre vents.

### 3. Tyres - 1.5mm Legal, 7-8mm New Average

- L.F

**Comment:** 6.3mm.

- R.F

**Comment:** 6.3mm.

- L.R

**Comment:** 6.0mm.

- R.R

**Comment:** 6.3mm.

- Spare

**Comment:** 2.7mm. Space saver wheel supplied.

**Advisory** - Wheels

**Comment:** Curbing scrapes on alloy wheels.





#### 4. Underbody

**Pass** - Chassis/Mountings



#### 5. Brakes

**Fail** - Master Cylinder

**Comment:** Brake and clutch fluid moisture content elevated. Replacement recommended.

**Pass** - Disc Pads (where visible)

**Comment:** Brake pads and discs in good condition.

## 6. Motor

### Pass - Valve Train

**Comment:** Timing belt drive engine. Decal indicates change completed at 96,294km.



### Fail - Oil Leaks

**Comment:** Oil leak around rear main seal.



### Pass - Oil Condition

**Comment:** Next service due at 114,100km.

- Oil Level

**Comment:** Oil level correct.



## 7. Road Test

**Pass** - Gearbox

**Comment:** Gearknob not secure.

**Advisory** - Foot Brake

**Comment:** Scraping noise from left front brake.

- WOF Expiration date

**Comment:** 15/10/2025.

- Registration Due:

**Comment:** 15/03/2025.

## 8. Body & Trim

**Pass** - Doors

**Comment:** No central locking fitted.

**Fail** - Jack

**Comment:** No jack sighted.

**Pass** - Seats

**Comment:** Drivers seat belt slow to retract.

- Other

**Comment:** Hole in soft top near rear window. 2 wear holes in drivers side of roof. Soft top has shrunk back.





## 9. Body Report

**Advisory** - Scratches/Abrasions

**Comment:** Scratch on right front bumper corner.



**Advisory** - Dents

**Comment:** Small dents in doors.

- Paint Repair Done

**Comment:** Paint repairs noted to front bumper, right front guard and hard top roof. Some overspray and paint shrinkage noted.



- Rust Repair Done

**Comment:** No rust repairs evident.

- Accident Repair Done

**Comment:** No accident repairs evident.